

GARMIN®

Navigation Data Alert 26112

TO: Users of the Garmin Navigation Database
DATE: July 15, 2026
CYCLE: 2607
AIRPORT: N/A
SUBJECT: Airway Information Updated Due to Suriname Late Source

PRODUCT AFFECTED

Cycle 2607 of the Garmin Navigation Database (effective 09 JUL 2026 to 06 AUG 2026) is affected.



NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The Airways data are out of date.

Table 1.

Airways	Corrections
UA555	• MAA changed from UNLTD to FL660
UA312	• MAA changed from UNLTD to FL660 • Course 'from' changed from 355 to 356 • Distance changed from 193 nm to 194 nm
UG449	• MAA changed from UNLTD to FL660 • Course 'from' changed from 146 to 143 • MEA changed from FL245 to FL200
UL306	• MAA changed from UNLTD to FL660 • Course 248 added, and a 41nm distance • MEA changed from NESTB to FL245
UG443	• MAA changed from UNLTD to FL660 • Course 'from' changed from 126 to 127 • MEA changed from FL245 to FL240
UM786	• MAA changed from UNLTD to FL660 • Course 'from' changed from 352 to 341 • MEA changed from FL290 to FL245
UM791	• MAA changed from UNLTD to FL660 • MEA changed from FL290 to FL245

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://www.flygarmin.com) and select "Aviation Data Error Report."

GARMIN®

Navigation Data Alert 26112

Table 1.

Airways	Corrections
UM527	• MAA changed from UNLTD to FL660 • MEA changed from FL290 to FL245
UL776	• MAA changed from UNLTD to FL660 • MEA changed from FL290 to FL245
UL452	• MAA changed from UNLTD to FL660 • MEA changed from FL290 to FL245
UL576	• MAA changed from UNLTD to FL660 • MEA changed from FL290 to FL245
UL462	• MAA changed from UNLTD to FL660 • MEA changed from FL290 to FL245

PILOT ACTION

Use the airways with caution.

RESOLUTION

The airways will be corrected in the 2608 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."