

# SERVICE ADVISORY

NO.: 1749 Rev A

TO:Registered Garmin G500/G600/G500H Owners and OperatorsDATE:September 20, 2017SUBJECT:TFR (Temporary Flight Restriction) Over FIS-B Data May Show Incorrect Time and Date

# PRODUCTS AFFECTED

G600/G500/G500H units that are interfaced with any FIS-B weather source (GDL 88, GTX 345/R, etc.) are affected.

### ISSUE

The time/date format on some broadcasted FIS-B TFRs may not be correct. If the time/date format is not correct, the time/date on the MAP and Weather page will not be correct.

### PILOT ACTION

Use the full TFR text to check the time/date.

- 1. Select and highlight a TFR on the map using the dual-concentric knob.
- 2. Push ENT to open the Airspace Information page.
- 3. Select TFR in the list (if there are multiple).
- 4. Push the "View Text" sofkey.
- 5. View the full text of the TFR to see the correct time and date.

Contact Air Traffic Control or Flight Service if you have any question about a TFR time/date.

# **RESOLUTION**

This issue will be addressed in a future software release.