

!! URGENT!!

Date: 26 February 2018

Subject: Krakow, Poland

Balice (EPKK)

RNAV (GNSS) RWY 25 [R25]

Cycle 1803

Speed Limit incorrect

Jeppesen NavData for cycle 1803, effective 1 March 2018, contains an incorrect Speed Limit at KK493 and KK494 waypoints on the RNAV (GNSS) RWY 25 [R25] approach procedure for Balice; Krakow, Poland (EPKK). The Speed Limit at **KK493** and **KK494** should be "**MAX 220 KT**".

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 1804, effective 29 March 2018. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: Notices and Alerts. Please refer to the Krakow, Poland (EPKK) 12-2 chart dated 23 FEB 18 (effective 1 March 2018) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

+1-303-328-4445 (Western Hemisphere) +49 610 250 8175 (Eastern Hemisphere)

E-mail: navdatatechsupport@ieppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.