

# GARMIN<sup>®</sup>

## Navigation Data Alert

**DATE:** 6 April 2018  
**CYCLE:** 1804, Effective 29 MAR 2018 to 26 April 2018  
**SUBJECT:** Incorrect Waypoint Coordinates on the VITAN1 SID

---

### **DESCRIPTION**

Garmin has been made aware that the following procedure contains a waypoint with incorrect coordinates:

| <b>Waypoint</b> | <b>Error</b>   |
|-----------------|--|
| TG005           | Coordinates should be<br>N14° 12' 34.863" W087° 40' 58.56" |

| <b>Airport</b> | <b>Procedure</b> |
|----------------|------------------|
| MHTG           | VITAN1 SID       |

This alert applies to the 1804 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

### **PILOT ACTION**

Do not use the procedure in any manner

### **RESOLUTION**

The coordinates will be corrected in the 1805 cycle of the Garmin Navigation Database.

**THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION  
UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE**

*Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [fly.garmin.com](http://fly.garmin.com) and select "[Aviation Data Error Report](#)."*