

!! URGENT !!

Date: 21 May 2018

Subject: Cleveland, Ohio Cleveland – Hopkins Intl (KCLE) ILS or LOC Rwy 24L [I24L] & [L24L] ILS or LOC Rwy 24R [I24R] & [L24R] Cycle 1806

Speed Restriction Missing at WIINR Waypoint

Jeppesen NavData for cycle 1806, effective 24 May 2018, does not contain a speed restriction at waypoint WINR on the BUDRW transition of the ILS or LOC Rwy 24L [I24L] & [L24L] and the ILS or LOC Rwy 24R [I24R] & [L24R] at Cleveland - Hopkins Intl; Cleveland, Ohio (KCLE). The speed restriction at **WIINR** waypoint is **MAX 210 kts**.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 1807, effective 21 Jun 2018. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site (<u>http://www.jeppesen.com/company/alerts/alerts.jsp</u>.

Please refer to the Cleveland, Ohio (KCLE) 11-6 ILS or LOC Rwy 24L chart dated 1 Jun 18 and the 11-9 ILS or LOC Rwy 24R chart dated 1 Jun 18 for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: Phone: 1-303-328-4445 E-mail: <u>navdatatechsupport@jeppesen.com</u>

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.