



## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered GDL 69/69(A)(H) Owners  
**DATE:** October 16, 2018  
**SUBJECT:** GDL 69/69(A)(H) SXM Upgrade to Software Version 5.21 for Non-GX000 Integrated Flight Deck Installations

### **PRODUCTS AFFECTED**

GDL 69 SXM (Garmin P/N 011-03177-00), GDL 69A SXM (Garmin P/N 011-03177-10), GDL 69H SXM (Garmin P/N 011-03177-20), and GDL 69AH SXM (Garmin P/N 011-03177-30) units with software version 5.10 or earlier that are not installed as part of a GX000 Integrated Flight Deck System.

### **PURPOSE**

GDL 69 series software version 5.21 contains the following changes:

- Removes unsubscribed channels from program and channel lists when interfacing with older display versions
- Increases reliability for transmission of METARS and PIREPS
- Fixes bug that limited weather packages for certain displays

### **COMPLIANCE**

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.