



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## SERVICE ADVISORY

NO.: 0617 Rev B

**TO:** All Garmin Datalink Product Owner/Operators  
**DATE:** December 10, 2018  
**SUBJECT:** Temporary Flight Restriction (TFR)  
**REVISION B:** Made advisory specific to all Garmin datalink products

---

### **PRODUCT AFFECTED**

All Garmin datalink products are affected.

### **ISSUE**

TFR data received through Garmin datalink products may be incomplete or out of date.

### **RESOLUTION**

TFR data received through Garmin datalink products is advisory in nature only and not a replacement for a thorough preflight briefing on TFR times and locations. Always confirm TFR data through official sources and contact your local Flight Service Station for interpretation of TFR data.

© 2018 Garmin Ltd. or its subsidiaries.  
This work is licensed under a  
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.