



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GFC 500 Owner and Operators
DATE: December 3, 2018
SUBJECT: G5 Software Version 5.70 (including GMC 507 Software Version 2.60)
CERTIFICATION AUTHORIZATION: AML STC SA01866WI

COMPLIANCE

Mandatory: This STC Service Bulletin is mandatory for GFC 500 systems installed per Part 23 AML STC SA01866WI.

PURPOSE

G5 Software Version 5.70 (including GMC 507 Software Version 2.60) updates the internal pre-flight test (PFT) process.

PRODUCTS AFFECTED

GFC 500 systems installed under GFC 500 Part 23 AML STC SA01866WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.