

Navigation Data Alert

DATE: 07 January 2019

CYCLE: 1901, Effective 03 JAN 2019 to 31 JAN 2019

SUBJECT: Incorrect Missed Approach Altitude on Procedure

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with incorrect altitude on the missed approach:

Airport	Procedure	Error
SAZN	VOR Y RWY 09 (S09-Y)	The missed approach requires a climb to 3600 on radial 120 before turning right direct to NEU VOR

This alert applies to the 1901 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with caution

RESOLUTION

The procedure will be corrected in the 1902 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."