

GARMIN[®]

Navigation Data Alert

DATE: 08 February 2019
CYCLE: 1902, Effective 31 JAN 2019 to 28 FEB 2019
SUBJECT: Incorrect Missed Approach Point

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with the incorrect missed approach point:

Airport	Procedure	Error
KSJT	VOR/DME RWY 3 (D03)	The procedure was delivered with the incorrect missed approach point. The missed approach point should be 3.3 nm (DME distance) from SJT VORTAC.

This alert applies to the 1902 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Do not use the procedure.

RESOLUTION

The procedure will be corrected in the 1903 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."