

SERVICE ADVISORY

NO.: 1930 Rev A

TO:GPS 155XL, GNC 250XL, and GNC 300XL Owners and OperatorsDATE:April 16, 2019SUBJECT:GPS 155XL, GNC 250XL, and GNC 300XL End of Service Life

PRODUCTS AFFECTED

Garmin GPS 155XL, GNC 250XL, and GNC 300XL units are affected.

ISSUE

Repair services and service parts will be discontinued for the units listed below. Repairs will be made as long as parts are available. As a reminder display repair services have been discontinued since 9/1/15.

Model	Estimated End of Service Life Date
GPS 155XL	12/15/2020
GNC 250XL	2/27/2020
GNC 300XL	2/28/2021

We sincerely regret discontinuing service or support on any Garmin product. However, a number of components required for the manufacture and/or repair of essential subassemblies within the affected products are no longer available.

Please visit <u>www.Garmin.com/aviation</u> for your product replacement needs.