



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered G500/G600 Owner and Operators  
**DATE:** May 2, 2019  
**SUBJECT:** Approval of GDU 620 software version 7.36 for Part 23 AML STC SA02153LA-D  
**CERTIFICATION AUTHORIZATION:** STC SA02153LA-D

---

### **COMPLIANCE**

Optional: This STC Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

### **PURPOSE**

This update includes:

- GDU 620 software version 7.36:
  - Added GSU 75 configuration options for AHRS installation, GPS antenna installation, and Center of Gravity locations
  - Added dual-ADHRS Miscompare Monitor configuration setting
  - Added CDI & BARO SYNC configuration setting
  - Added CDI SYNC WITH NAVIGATOR configuration setting
  - Added support for GWX 70 Ground Clutter Suppression and Turbulence Detection features when configured for a 10" antenna
  - Minor bug fixes and improvements to existing functionality.
  - Fixed a bug with autopilot capture

### **PRODUCTS AFFECTED**

G500/G600 systems installed under the G500/G600 Part 23 AML STC SA02153LA-D are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.