

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot using the US or North America FliteCharts database

DATE: June 11, 2019

CYCLE: 1907

SUBJECT: Corrected charts for COASTAL SEVEN Departure

DESCRIPTION

The FAA has advised Garmin that the digital-Terminal Procedures Publication, effective June 20, 2019, incorrectly depicts the departure route from HFD VOR/DME to CCC VOR/DME for the COASTAL SEVEN departure charts.

This departure serves the following airports:

- Bradley Intl, Windsor Locks, CT (KBDL)
- Hartford-Brainard, Hartford, CT (KHFD)
- Westfield-Barnes Rgnl, Westfield/Springfield, MA (KBAF)

The original safety alert can be seen at the following link:

https://www.faa.gov/air_traffic/flight_info/aeronav/safety_alerts/media/TERM_19-11_SA_COASTAL_DP.pdf

PILOT ACTION

Do not use the COASTAL SEVEN departure charts in US or North America FliteCharts.

RESOLUTION

The charts will be corrected in the 1908 cycle, effective July 18, 2019, of the US and North America FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot.

FAA Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE US OR NORTH AMERICA FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."