

!! URGENT !!

Date: 16 July 2019 Subject: Japan Enroute Airway

Cycle 1908

Enroute airway data incorrectly coded

Jeppesen NavData for cycle 1908, effective 18 July 19 contains an incorrect airway direction indication for Airway Y804 within Japan.

Y804 should be one way westbound between LALID NCRP and INUBO NCRP.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 1909, effective 15 August 19. Until then an entry will appear in the Navdata Change Notices, and this Alert will be posted on the Jeppesen Web site (<u>http://www.jeppesen.com/company/alerts/alerts.jsp</u>).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: Phone: 303-328-4445 E-mail: <u>navdatatechsupport@jeppesen.com</u>

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.