

GARMIN[®]

Navigation Data Alert

DATE: 15 August 2019
CYCLE: 1909, Effective 15 AUG 2019 to 12 SEP 2019
SUBJECT: Fix Removed from Airway

DESCRIPTION

Garmin has been made aware that the following airway was delivered with an incorrectly removed waypoint.

Airway	Error
J37	FAA NASR Safety Alert 19-14 states that PEKON, between HEIGH and HRV VORTAC was incorrectly removed from the airway in the 1909 cycle.

This alert applies to the 1909 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the airway with extreme caution

RESOLUTION

The airway will be corrected in the 1910 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."