



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered GFC 600 Owner and Operators  
**DATE:** November 12, 2019  
**SUBJECT:** GSA 87 Software and Gain file update for Textron Aviation (Cessna) 208B with a Cargo Pod  
**CERTIFICATION AUTHORIZATION:** STC SA01844WI

---

### **COMPLIANCE**

Mandatory: This STC Service Bulletin must be accomplished at the next scheduled service interval.

### **PURPOSE**

The GSA 87 gain file has been updated to provide better roll axis performance.

### **PRODUCTS AFFECTED**

GFC 600 systems installed under the GFC 600 Part 23 AML STC SA01844WI in Textron Aviation (Cessna) 208B with cargo pod are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.