



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G500/G600 TXi Owners and Operators
DATE: December 11, 2019
SUBJECT: Approval of G500/G600 TXi Software Version 3.03
CERTIFICATION AUTHORIZATION: STC SA02571SE

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

This STC Service Bulletin announces the approval of G500/G600 TXi Software Version 3.03.

G500/G600 TXi Software Version 3.03 includes the following changes:

- Fixed a condition that could cause a GDU 700P configured as a Standby PFD to skip the database verification screen
- Fixed the condition which required the G5 Standby interface to be deconfigured in certain circumstances
- Added label 171P to ARINC 429 General Purpose Output 1

PRODUCTS AFFECTED

G500/G600 TXi PFD/MFD/EIS display systems installed using Approved Model List (AML) Supplemental Type Certificate (STC) SA02571SE are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.