



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GI 275 Owners and Operators
DATE: February 5, 2020
SUBJECT: GI 275 Multi-function Instrument Software Version 2.03
CERTIFICATION AUTHORIZATION: STC SA02658SE

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

This STC Service Bulletin provides notification of STC SA02658SE Master Drawing List revision 2 update.

Updates include:

- GI 275 Software version 2.03 provides automatic flight logs to fly.garmin and live engine data streaming to Garmin Pilot with v10.0.
- Updated Analog CDI Interconnect with correct plug and pin numbers and clarified interface only provides Nav and not GPS.
- Updated Appendix D column heading and marked the Reims Aviation F406 for standby ADI or MFD only installations.

PRODUCTS AFFECTED

GI 275 Multi-function Instrument installed under the GI 275 Part 23 AML STC SA02658SE are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.