

GARMIN[®]

Navigation Data Alert

DATE: 02 March 2020
CYCLE: 2003, Effective 27 FEB 2020 to 26 MAR 2020
SUBJECT: Incorrect Departure Route

DESCRIPTION

Garmin has been made aware that Chile's coding table incorrectly switched RWY 17L and RWY 17R on the following departure:

Airport	Procedure	Error
SCEL	LINER 3C Departure	The initial departure fixes for RWY 17L and 17R were inadvertently swapped. The correct route for RWY 17L is to DESIT and RWY 17R is to VAGOS.

This alert applies to the 2003 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Do not use the procedure in any manner.

RESOLUTION

The procedure will be corrected in the 2004 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."