

## **SERVICE ADVISORY**

**NO.: 2077 Rev A**

**TO:** GTN 625Xi/635Xi/650Xi Owners and Operators  
**DATE:** June 10, 2020  
**SUBJECT:** Replying to an SMS Text Message

---

### **PRODUCTS AFFECTED**

GTN 625Xi/635Xi/650Xi products with Software Version 20.01, installed with a GSR 56 are affected.

### **ISSUE**

The send button is missing when replying to an SMS message received through a GSR 56.

### **ACTION**

Be aware the send button is missing when replying to an SMS message.

**NOTE**

The ability to compose and send a new SMS message is not affected by this issue.

### **RESOLUTION**

This issue will be corrected in a future GTN 625Xi/635Xi/650Xi software version.