

GARMIN[®]

Navigation Data Alert

DATE: 18 June 2020
CYCLE: 2007 Effective 18 JUN 2020 to 16 JUL 2020
SUBJECT: Missing Crossing Altitude Restriction

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with a missing crossing altitude restriction:

Airport	Procedure	Error
PHNY	VOR OR TACAN RWY 3 (S03)	A crossing restriction between 6000' and 3700' was omitted at LNY prior to executing the procedure turn.

This alert applies to the 2007 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with extreme caution

RESOLUTION

The procedure will be corrected in the 2008 cycle of the Garmin Navigation Database.

**THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION
UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE**

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."