



## **!! URGENT !!**

**Date:** 17 June 2020

**Subject:** Portland, Oregon  
Portland Intl (KPDX)  
TACAN Rwy 28L

***Procedure Coding Unusable***

Jeppesen NavData for cycle 2006, effective 21 May 2020, and cycle 2007, effective 18 June 2020, contains incorrect NavData coding for the TACAN Rwy 28L procedure.

**THEREFORE, DO NOT USE THE TACAN RWY 28L PROCEDURE IN NAVDATA CYCLES 2006 AND 2007.**

Revised coding will appear in Jeppesen NavData for cycle 2008, effective 16 July 2020. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site. <http://www.jeppesen.com/company/alerts/alerts.jsp>

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
Phone: 1-303-328-4445  
E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.