



## !! URGENT !!

**Date:** 28 August 2020

**Subject:** Madrid, Spain  
Adolfo Suarez Madrid-Barajas (LEMD)  
SOMOSIERRA 2W DEPARTURE [SIE2W]  
Cycle 2009 and 2010

*Fly-by coded incorrectly*

Jeppesen NavData for cycle 2009 (effective 13 August 2020) and 2010 (effective 10 September 2020), contains an incorrectly coded fly-by on waypoint D017F on the SOMOSIERRA 2W [SIE2W] SID at Adolfo Suarez Madrid-Barajas; Madrid, Spain (LEMD). Waypoint **D017F** is a **fly-over**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO  
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2011, effective 08 October 2020. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Madrid, Spain (LEMD) Chart 10-3V3, dated 17 JUL 20 for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

LEMD\_2009\_2010