

GARMIN[®]
1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GFC 500 Owners and Operators
DATE: September 22, 2020
SUBJECT: Update to GFC 500 STC to add GI 275 interface
CERTIFICATION AUTHORIZATION: STC SA01866WI

COMPLIANCE

Optional: This STC Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

STC SA01866WI Master Drawing List revision 39 includes the following:

- Addition of the GI 275 as the display and control head for the GFC 500.

PRODUCTS AFFECTED

GFC 500 autopilots installed under the GFC 500 Part 23 AML STC SA01866WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.