



!! URGENT !!

Date: 21 September 2020

Subject: Francistown, Botswana
Francistown (FBFT)
RNAV (GNSS) RWY 31
Cycle 2010 and 2011

Procedure unusable

Jeppesen NavData for cycles 2010 and 2011, effective 10 September 2020, contains incorrect data for Francistown Airport; Francistown, Botswana (FBFT). Instrument approach procedure RNAV (GNSS) RWY 31 should not be used. SUP 23-20, Effective 01 SEP 20 was received after the ICAO specified date for aeronautical information publication.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2012, effective 05 November 2020. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.