

GARMIN® Navigation Data Alert

DATE: 14 October 2020
CYCLE: 2011, Effective 08 OCT 2020 to 05 NOV 2020
SUBJECT: Incorrect LPV Service Level Data

DESCRIPTION

Garmin has been made aware that the following procedures were delivered with incorrect data causing the LPV service level to be unusable:

Heliport	Procedures	Error
25TN	Copter RNAV (GPS) 235	Incorrect final approach course data
91PA	Copter RNAV (GPS) 110	Incorrect final approach course data
4OH2	Copter RNAV (GPS) 022	Incorrect final approach course data
LL84	Copter RNAV (GPS) 078	Incorrect final approach course data

This alert applies to the 2011 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Do not use the procedures in any manner

RESOLUTION

The procedures will be corrected in the 2012 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."

SN 25TN,91PA,4OH2,LL84-2011