

DATE: 3 November 2020

CYCLE: 2011 & 2012, Effective 08 OCT 2020 to 03 DEC 2020

SUBJECT: Incorrect LPV Service Level Data

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with incorrect data causing the LPV service level to be unusable:

Airport	Procedures	Error
KDOV	RNAV (GPS) RWY 32	Incorrect final approach course data

This alert applies to the 2011 & 2012 cycles of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Do not use the procedure in any manner

RESOLUTION

The procedure will be corrected in the 2013 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."