



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G5 Owners and Operators
DATE: January 4, 2021
SUBJECT: G5 Electronic Flight Instrument Software Version 6.82
CERTIFICATION AUTHORIZATION: STC SA01818WI

COMPLIANCE

Recommended. This service bulletin is recommended for G5 systems installed per Part 23 AML STC SA01818WI.

PURPOSE

G5 Software version 6.82 for certified installations includes an update that adds support for the new G5 battery packs (p/n 011-03893-01). This issue is described in Garmin Service Advisory 20126.

PRODUCTS AFFECTED

G5 systems installed under G5 Part 23 AML STC SA01818WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.