



JEPPesen®

Information Alert

!! URGENT !!

UPDATED FOR Cycle 2101

Date: 27 January 2021

Subject: NOTAM guide for the following airports:

**Mexico City, Mexico; Benito Juarez Intl (MMMX)
Toluca, Mexico; Lic Adolfo Lopez Mateos Intl (MMTO)
Cuernavaca, Mexico; Gen Mariano Matamoros Intl (MMCB)
Puebla, Mexico; Hermanos Serdan Intl (MMPB)
Guadalajara, Mexico; Miguel Hidalgo y Costilla Intl, (MMGL)**

The tables below list the terminal instrument procedures authored/released by Jeppesen for AIRAC Cycle 2101 (Eff 28 JAN 21), at MMMX, MMTO, MMCB, MMPB and MMGL airports. In accordance with current Mexico NOTAMs (published as of 01/26/2021), the tables below indicate the usability of the charts and coding for the listed procedures.

Note: Further changes initiated by Mexico prior to or after the AIRAC Cycle effective date of 28 January, 2021 could affect the accuracy of the information provided in the tables below. For this reason, Mexico NOTAMs and Jeppesen Chart/NavData change notices should be monitored.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS IMMEDIATELY!**

This information alert is also posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@jeppesen.com

Alerts are published to advise users of significant issues in Jeppesen chart and data which may affect aircraft operations. Alerts are distributed to Jeppesen customers and are also available on Jeppesen's Web site at www.jeppesen.com.

The tables shown below list the instrument procedures authored/released by Jeppesen for **AIRAC Cycle 2101 (Eff 28 Jan 21)**, at MMMX, MMT0, MNCB, MMPB, MMGL airports in accordance with current Mexico NOTAMs (published as of 01-26-2021). The usability of the procedures are as follows for **AIRAC Cycle 2101**:
RED = Unusable; GREEN Usable

Location				
MMCB	Cuernavaca, Gen Mariano Matamoros Intl			
Jepp Chart	Procedure names	Chart Usable Y/N	NavData Usable Y/N	Relevant NOTAM
STARs				
10-2	OTIVO1A, SIKMO1A	NO	NO	A0103/21
10-2A	OTIVO1B, SIKMO1B	NO	NO	A0103/21
SIDs				
10-3	RWY 03. DEPS (CUA 1E, CVJ 1A, TEQ 1C)	YES	YES	
10-3A	RWY 21 DEPS (CUA 1F, CVJ 1B, MAXUL 1C, TEQ 1D)	YES	YES	
10-3B	OTIVO1C, SIKMO1C	NO	NO	A0103/21
10-3C	OTIVO 1D, SIKMO 1D	NO	NO	A0103/21
APPROACH PROCEDURES				
12-1	RNP RWY 03	NO	NO	A0103/21
12-2	RNP RWY 21	NO	NO	A0103/21
13-1	VOR DME RWY 03	YES	YES	
Location				
MMPB	Puebla, Hermanos Serdan Intl			
Jepp Chart	Procedure names	Chart Usable Y/N	NavData Usable Y/N	Relevant NOTAM
STARs				
10-2	ATUKA 1A, LARLO 1C, TAKAL 1A	NO	NO	A0101/21
10-2A	ATUKA 1B, LARLO 1D, TAKAL 1B	NO	NO	A0101/21
SIDs				
10-3	ALITA 2, ALMET 1, PUEBLA 2B	YES	YES	
10-3A	ATUKA, ILETO, NOXOS, TAKAL, UKUNO 1C	NO	NO	A0101/21
10-3B	ATUKA, ILETO, NOXOS, TAKAL, UKUNO 1D	NO	NO	A0101/21
10-3C	MAPEN2, PUEBLA 3A	YES	YES	
APPROACH PROCEDURES				
12-1	RNP RWY 17	NO	NO	A0101/21
12-2	RNP RWY 35	NO	NO	A0101/21
13-1	VOR DME 1 RWY 17	YES	YES	

If you have any questions concerning this Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@jeppesen.com

Alerts are published to advise users of significant issues in Jeppesen chart and data which may affect aircraft operations. Alerts are distributed to Jeppesen customers and are also available on Jeppesen's Web site at www.jeppesen.com.

13-2	VOR DME 2 RWY 17	YES	YES	
13-3	VOR DME 1 RWY 35	YES	YES	
13-4	VOR DME 2 RWY 35	YES	YES	
13-5	VOR A	YES	YES	

Location				
MMTO	Toluca, Lic Adolfo Lopez Mateos Intl			
Jepp Chart	Procedure names	Chart Usable Y/N	NavData Usable Y/N	Relevant NOTAM
STARs				
10-2B	DERVI 4	YES	YES	
10-2C	ELILA 1A, ITLAS 1A	NO	NO	A0100/21
10-2C1	ELILA 1B, ILAXA 1A, ITLAS 1B	NO	NO	A0100/21
10-2D	LENUL 1A	NO	NO	A0100/21
10-2E	MEXICO 4C	YES	YES	
10-2E1	MEXICO 3D	YES	YES	
10-2E2	PASTEJE 3, TAKUG 1	YES	YES	
10-2F	URTOV 4A	YES	YES	
10-2G	URTOV3B	YES	YES	
SIDs				
10-3	DEPARTUES RWY 15 (APN 3C, CUA 2B, MAXUL 5A, PTJ 2C, TEQ 2A, TLC 4D)	YES	YES	
10-3A	DEPARTURES RWY 33 (APN 3D, CUA 2C, MAXUL 5B, PTJ 2D, TEQ 2B, TLC 6E, ZARCO 5A)	YES	YES	
10-3B	RNAV DEPARTURES RWY 15 (OMPER 1A, OVAGO 1C, PURAL 1A, SEBON 1C, TEVOS 1C, ULEBA 1C)	NO	NO	A0100/21
10-3C	RNAV DEPARTURES RWY 33 (KEBSO 1A, OVAGO 1D, SEBON 1D, TEVOS 1D, ULEBA 1D)	NO	NO	A0100/21
APPROACH PROCEDURES				
11-1	ILS DME 1 OR LOC RWY 15	YES	YES	
11-2	ILS DME 2 OR LOC RWY 15	YES	YES	
11-2A	ILS DME RWY 15 CAT II & IIIA	YES	YES	
11-3	ILS Z ORLOC RWY 15	NO	NO	A0100/21
12-1	RNP RWY 15	NO	NO	A0100/21
12-2	RNP RWY 33	NO	NO	A0100/21
13-1	VOR DME 1 RWY 15	YES	YES	
13-2	VOR DME 2 RWY 15	YES	YES	
13-3	VOR DME 1 RWY 33	YES	YES	
13-4	VOR DME 2 RWY 33	YES	YES	
13-5	VOR-A	YES	YES	

If you have any questions concerning this Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@jeppesen.com

Alerts are published to advise users of significant issues in Jeppesen chart and data which may affect aircraft operations. Alerts are distributed to Jeppesen customers and are also available on Jeppesen's Web site at www.jeppesen.com.

Location				
MMGL	Guadalajara, Miguel Hidalgo y Costilla Intl			
Jepp Chart	Procedure names	Chart Usable Y/N	NavData Usable Y/N	Relevant NOTAM
STARs				
10-2B	LIPEP 1F, LONVA 1C, USBIM 1C	NO	NO	A0098/21
10-2C	LIPEP 1G, ULUVO 1B, USBIM 1D	NO	NO	A0098/21
10-2D	LIVRI 1C, MODEX 1A, ULUVO 1A	NO	NO	A0098/21
10-2E	LIVRI 1D, LONVA 1D, MODEX1B	NO	NO	A0098/21
SIDs				
10-3	DEPARTURES RWY 10 (EMIGU 2A, EBDEG 1, GOYAS 3A, GDL 4A, KARUN 1, LEROK 3, OVALI 4, PIRAR 3, TABGO 3A, XORID 2)	YES	YES	
10-3A	DEPARTURES RWY 28 (DEBRO 2, DUNSU 2, EMIGU 2B, GOYAS 3B, GDL 4B, NUBIG 2, TABGO 3B, TEILA 3, TIKIT 3)	YES	YES	
10-3D	EMIRI, FEISE, KELVA, OTOKI 1A, LONKU 1D	NO	NO	A0098/21
10-3E	EMIRI, FEISE, KELVA, OTOKI 1B, LONKU 1E	NO	NO	A0098/21
10-3F	GUADALAJARA 2C	YES	YES	
10-3G	NOTUP 1D, SEDEM 1A	NO	NO	A0098/21
10-3H	NOTUP 1E, SEDEM 1B	NO	NO	A0098/21
APPROACH PROCEDURES				
11-1	ILS DME 1 or LOC Rwy 10	YES	YES	
11-2	TRANS FOR ILS DME 2 OR LOC RWY 10	YES	YES	
11-2A	ILS DME 2 OR LOC RWY 10	YES	YES	
11-3	ILS DME 1 OR LOC RWY 28	YES	YES	
11-4	TRANS FOR ILS DME 2 OR LOC RWY 28	YES	YES	
11-4A	ILS DME 2 OR LOC RWY 28	YES	YES	
11-5	ILS DME 3 OR LOC RWY 10	NO	Not in Database	A7514/20
11-6	ILS DME 3 OR LOC RWY 28	NO	Not in Database	A7514/20
11-7	ILZ Z OR LOC Z RWY 10	NO	NO	A0098/21
11-8	ILS Z RWY 28	NO	NO	A0098/21
12-1	RNP Z RWY 10	NO	NO	A0098/21
12-2	RNP RWY 10	NO	Not in Database	A7514/20
12-3	RNP Z RWY 28	NO	NO	A0098/21
12-4	RNP RWY 28	NO	Not in Database	A7514/20
13-1	VOR DME 1 RWY 10	YES	YES	
13-2	TRANS FOR VOR DME 2 RWY 10	YES	YES	
13-2A	VOR DME 2 RWY 10	YES	YES	
13-3	VOR DME 1 RWY 28	YES	YES	

If you have any questions concerning this Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@jeppesen.com

Alerts are published to advise users of significant issues in Jeppesen chart and data which may affect aircraft operations. Alerts are distributed to Jeppesen customers and are also available on Jeppesen's Web site at www.jeppesen.com.

13-4	TRANS FOR VOR DME 2 RWY 28	YES	YES	
13-4A	VOR DME 2 RWY 28	YES	YES	
18-1	RADAR ASR RWY 10,28	YES	Not in Database	

Location				
MMMX	Mexico City; Benito Juarez Intl			
Jepp Chart	Procedure names	Chart Usable Y/N	NavData Usable Y/N	Relevant NOTAM
STARs				
10-2	AVSAR 4A, DATUL 4A, SASUT 1A, TIKEB 1A	YES	YES	
10-2A	ASVAR 3B, DATUL 3B, SASUT 1B, TIKEB 1B	YES	YES	
10-2B	DARAN 1A, ESPOS 1A	NO	NO	A0099/21
10-2B1	DARAN 1B, ENAGA 1B	NO	NO	A0099/21
10-2C	DUXOP 1	YES	YES	
10-2C1	ENAGA 1A, LARLO 1A	NO	NO	A0099/21
10-2C2	ESPOS 1B, LARLO 1B	NO	NO	A0099/21
10-2D	MEXICO 5A	YES	YES	
10-2E	MEXICO 3B	YES	YES	
10-2F	PACHUCHA 1A, SANTA LUCIA 1A	YES	YES	
SIDs				
10-3	DEPS RWY 05L/R	YES	YES	
10-3A	APAN 5B, OTMOS 1, PUEBLA 3D	YES	YES	
10-3B	PASTEJE 5B, TOLUCA 6B, & 4C	YES	YES	
10-3C	RNAV DEPS RWY 05L/R (ATUR1A, AXIR1A, IKLA1A, ILET1A, NOXO1A, OVAG1A, SEBO1A, TEVO1A, UKUN1A, ULEB1A)	NO	NO	A0099/21
10-3D	RNAV DEPS RWY 23L/R (ATUR1B, AXIR1B, IKLA1B, ILET1B, NOXO1B, OVAG1B, SEBO1B, TEVO1B, UKUN1B, ULEB1B)	NO	NO	A0099/21
APPROACH PROCEDURES				
11-1	ILS DME 1 OR LOC RWY 5R	YES	YES	
11-3	ILS DME 1 OR LOC RWY 23L	YES	YES	
11-4	ILS DME 2 OR LOC RWY 23L	YES	YES	
11-5	ILS Z OR LOC RWY 05R	NO	NO	A0099/21
11-6	ILS Z OR LOC RWY 23L	NO	NO	A0099/21
12-1	RNP RWY 05L	NO	NO	A0099/21
12-2	RNP RWY 05R	NO	NO	A0099/21
12-3	RNP RWY 23L	NO	NO	A0099/21
12-4	RNP RWY 23R	NO	NO	A0099/21
13-1	VOR DME RWY 05R/L	NO	Not in Database	Jepp CCN Z3632/20

If you have any questions concerning this Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@jeppesen.com

Alerts are published to advise users of significant issues in Jeppesen chart and data which may affect aircraft operations. Alerts are distributed to Jeppesen customers and are also available on Jeppesen's Web site at www.jeppesen.com.

13-2	VOR DME RWY 23L/R	NO	Not in Database	Jepp CCN Z3632/20
18-1	RADAR ALL RWYS	YES	Not in Database	

If you have any questions concerning this Alert, please contact Chart Support at:

+1 (303) 328-6776 (Western Hemisphere)

+49 (6102) 50-8174 (Eastern Hemisphere)

U.S. Toll Free: 1-800-353-2107

E-mail: ChartSupport@jeppesen.com

Alerts are published to advise users of significant issues in Jeppesen chart and data which may affect aircraft operations. Alerts are distributed to Jeppesen customers and are also available on Jeppesen's Web site at www.jeppesen.com.