

1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G1000 NXi Equipped Textron Aviation 200/300 Series King Air Aircraft Owners and Operators

DATE: March 5, 2021

SUBJECT: System Software Version 2286.12 G1000 NXi Update for Textron Aviation 200/300 Series King Air Aircraft

COMPLIANCE

Optional. This service bulletin is optional and may be incorporated at the owner's discretion.

PURPOSE

The GMA 1360D dedicated PA and COM 3 audio configurations were inadvertently changed in system software version 2286.11.

PRODUCTS AFFECTED

All Textron Aviation Inc. (Beechcraft) King Air 200 and 300 series aircraft equipped with G1000 Integrated Flight Deck per STC SA01535WI-D with system software versions 2286.00 to 2286.11 are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.