

## **SERVICE ADVISORY**

**NO.: 2167 Rev A**

**TO:** GFC 600 AFCS Owners and Operators  
**DATE:** July 23, 2021  
**SUBJECT:** Overspeed Protection

---

### **PRODUCTS AFFECTED**

Garmin GFC 600 AFCS installed in Textron Aviation (Beechcraft) C90 are affected.

### **ISSUE**

Overspeed Protection will not engage until 226 KIAS. This is above the published Vne of the C90.

### **ACTION**

Never exceed the manufacturer published airframe speed limits.

### **RESOLUTION**

This will be fixed in a future software release.