

SERVICE ALERT

NO.: 21117 Rev B

TO: Owners/Operators of King Air 200/300 Series G1000 NXi STC SA01535WI-D Aircraft

DATE: December 10, 2021

SUBJECT: Aural Alerts Volume Low Over Speaker

REVISION B: Added Resolution

PRODUCTS AFFECTED

Textron Aviation Inc. (Beechcraft) King Air model B200, B200C, B200GT, B200CGT, 300, 300LW, B300, and B300C aircraft equipped with **all** of the following are affected:

- G1000 NXi Integrated Flight Deck per STC SA01535WI-D
- G1000 NXi System Software Version 2286.11, 2286.12, or 2286.13

NOTE

Use the FMS knob to select the 'AUX – System Status' page to view the System Software Version. The System Software Version is shown in the upper right box.

- GMA 1360 Audio Panel (See Figure 1)



Figure 1 – GMA 1360 Audio Panel

© 2021 Garmin Ltd. or its subsidiaries.

This work is licensed under a
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.

ISSUE

Aircraft aural alerts (Stall Warn / Gear / Cabin Altitude) volume over speakers may not be audible in flight.

PILOT ACTION

Wear a headset while flying.

RESOLUTION

Contact your local dealer for incorporation of Garmin STC Service Bulletin 21118.

