

SERVICE ALERT

NO.: 21121 Rev B

TO: Owners/Operators of King Air C90 Series G1000 NXi STC SA01456WI-D Aircraft

DATE: December 21, 2021

SUBJECT: Aural Alerts Volume Low Over Speaker

REVISION B: Added Resolution

PRODUCTS AFFECTED

Textron Aviation Inc. (Beechcraft) King Air model C90A, C90GT, and C90GTi aircraft equipped with **all** of the following are affected:

- G1000 NXi Integrated Flight Deck per STC SA01456WI-D
- G1000 NXi System Software Version 3557.00 or 3557.01

NOTE

Use the FMS knob to select the 'AUX – System Status' page to view the System Software Version. The System Software Version is shown in the upper right box.

- Aural Tone Generators
- GMA 1360 Audio Panels (See Figure 1)



Figure 1 – GMA 1360 Audio Panel

© 2021 Garmin Ltd. or its subsidiaries.
This work is licensed under a
Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.

ISSUE

Aircraft aural alerts (Stall / Gear) volume over speakers may not be audible in flight.

PILOT ACTION

Wear a headset while flying.

RESOLUTION

Contact your local dealer for incorporation of Garmin STC Service Bulletin 21122.