



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 21138 Rev A

TO: GI 275 Owners and Operators
DATE: January 5, 2022
SUBJECT: Display of FIS-B

PRODUCTS AFFECTED

GI 275 products with software versions 2.42 configured to show FIS-B weather data from a GNX™ 375 are affected.

ISSUE

The GI 275 shows a 'Receiver Failure' banner on the GI 275 FIS-B weather page.

ACTION

Use the GNX 375 display for FIS-B weather information.

RESOLUTION

This issue will be resolved in a future software release.

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/)..