

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot™ using the Australia or South Pacific FliteCharts® database
DATE: December 10, 2025
CYCLE: 2512
SUBJECT: MELBOURNE AERODROME (YMML) TAXILANE RENAMING

DESCRIPTION

Airservices Australia has advised Garmin that the APRON CHART PAGE 1 chart at Melbourne Airport (YMML), Victoria, Australia included in FliteCharts cycle 2512, effective November 27, 2025, does not depict amendments. A revised chart has been published in SUP H188/25, effective December 10, 2025.

The original AIP supplement can be seen at the following link:

<https://www.airservicesaustralia.com/aip/current/sup/s25-h188.pdf>

PILOT ACTION

Exercise caution when referencing the APRON CHART PAGE 1 chart at Melbourne Airport (YMML), Victoria, Australia in Australia or South Pacific FliteCharts for cycle 2512.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

RESOLUTION

The chart will be corrected in cycle 2513 of the Australia and South Pacific FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot. Cycle 2513 FliteCharts databases are effective December 25, 2025 and will be available December 23, 2025.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE AUSTRALIA OR SOUTH PACIFIC FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select [“Aviation Data Error Report.”](#)