

GARMIN[®]

SmartCharts Alert 25087

TO: Users of Garmin Pilot™ Mobile US and Worldwide for iOS
DATE: December 9, 2025
CYCLE: 2512
SUBJECT: Incorrect Altitude Constraint on RNAV (RNP) Y RWY 26 at KRIL

PRODUCT AFFECTED

The Garmin SmartCharts procedure for the RNAV (RNP) Y RWY 26 at KRIL, Rifle, CO, shown in Garmin Pilot Mobile iOS is affected.

DESCRIPTION

When the procedure is filtered to show only the TRUEL transition, the altitude constraint shown on the profile view at fix WIBEX is incorrect. An AT OR ABOVE 10100' altitude constraint is shown. The correct altitude constrain is AT OR ABOVE 10200'.

PILOT ACTION

Use caution when filtering the procedure to show only the TRUEL transition. Viewing all transitions (unfiltered) will show the proper constraints at WIBEX.

RESOLUTION

This SmartCharts procedure will be corrected in cycle 2513.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://flygarmin.com) and select "Aviation Data Error Report."