

GARMIN®

SmartCharts Alert 25086

TO: Users of Garmin Pilot™ Mobile US and Worldwide for iOS
DATE: December 9, 2025
CYCLE: 2512
SUBJECT: Missing Altitude and Speed Constraints on RNAV (RNP) Z RWY 13R at KSAT

PRODUCT AFFECTED

The Garmin SmartCharts procedure for the RNAV (RNP) Z RWY 13R at KSAT, San Antonio, TX, shown in Garmin Pilot Mobile iOS is affected.

DESCRIPTION

When the procedure is filtered to show only the SWUPZ transition, the altitude and speed constraints on the planview at fix RBNSN are missing. The correct altitude constraint is AT 6000' and the correct speed constraint is AT OR BELOW 210KT.

PILOT ACTION

Use caution when filtering the procedure to show only the SWUPZ transition. Viewing all transitions (unfiltered) will show the correct constraints at RBNSN.

RESOLUTION

This SmartCharts procedure will be corrected in cycle 2513.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://flygarmin.com) and select "Aviation Data Error Report."