

# GARMIN®

## Navigation Data Alert 25085

**TO:** Users of the Garmin Navigation Database  
**DATE:** December 09, 2025  
**CYCLE:** 2512  
**SUBJECT:** Incorrect Missed Approach Instructions

---

### **PRODUCT AFFECTED**

The Garmin Navigation Database cycle 2512 (effective November 27, 2025) is affected.



### **NOTE**

This Data Alert does not apply to the Jeppeson NavData database.

### **DESCRIPTION**

The WMKM (Malacca, Malaysia) Airport VOR Y RWY 21 missed approach has a course to a radial with an altitude constraint that is incorrect. The correct course is 60° to a radial of 150 from VMK VOR/DME. The correct altitude at the interception is at or above 5000 feet.

### **PILOT ACTION**

Use caution when flying the missed approach in cycle 2512.

### **RESOLUTION**

The procedure will be corrected in the 2513 cycle of the Garmin Navigation Database.

**THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE**

*Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.*

*Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](http://FlyGarmin.com) and select "Aviation Data Error Report."*