

GARMIN®

Navigation Data Alert 26061

TO: Users of the Garmin Navigation Database
DATE: June 9, 2026
CYCLE: 2606
AIRPORT: FVCZ - BUFFALO RANGE AIRPORT
SUBJECT: Incorrect Turn on Final

PRODUCT AFFECTED

Cycle 2606 of the Garmin Navigation Database (effective 11 JUN 2026 to 09 JUL 2026) is affected.



NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The following procedure has an incorrect turn on final.

Airport	Procedure	Error
FVCZ	N14	The procedure has an incorrect turn between the FAF and MAP.

PILOT ACTION

Do not use the procedure.

RESOLUTION

The procedure will be corrected in the 2607 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://www.flygarmin.com) and select "[Aviation Data Error Report](#)."