

GARMIN®

SmartCharts Data Alert 26064

TO: Users of the Garmin Pilot™ App US and Worldwide for iOS
DATE: June 11, 2026
CYCLE: 2606
SUBJECT: Incorrect Obstacle Departure Procedure notes for KTOA

PRODUCT AFFECTED

The Garmin SmartCharts procedure for the Obstacle Departure Procedures for Runway 29L and 29R at KTOA, Torrance, CA, shown in Garmin Pilot Mobile iOS are affected.

DESCRIPTION

When viewing the Obstacle Departure Procedures for Runway 29L and 29R, the Obstacle Departure Procedures note is missing additional text.

Missing Text:

“Both departures climb to 3000, intercept LAX R-170 to LIMBO Int.”

Correct Note:

“Rwys 29L/R, climb runway heading. Both departures climb to 3000, intercept LAX R-170 to LIMBO Int.”

PILOT ACTION

Use caution when using the Obstacle Departure Procedures for Runway 29L and 29R.

RESOLUTION

These SmartCharts Obstacle Departure Procedures can be corrected by downloading the cycle 2606 Navigation Database any time after June 11, 2026 at 10:00 AM CT.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS USING GARMIN SMARTCHARTS

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select “Aviation Data Error Report.”