

IFR/VFR Charts Data Alert

TO: Users of all Garmin aviation products using the United States or Central America IFR/VFR Charts databases
DATE: July 20, 2026
CYCLE: 2607
SUBJECT: Miami Aeronautical Charts Effective July 9, 2026 - Airspace at Miami Executive Airport (KTMB)

DESCRIPTION

The FAA has advised Garmin that the Miami VFR Sectional and Miami VFR Terminal Area charts effective July 9, 2026 have incorrect Class D and Class E airspace.

The original safety alert can be seen at the following link:

http://www.faa.gov/air_traffic/flight_info/aeronav/safety_alerts/media/VIS_Safety_Alert_Miami_Exec_Airspace.pdf

PILOT ACTION

Exercise caution when referring to airspaces on Miami VFR Sectional chart and Miami VFR Terminal Area chart near Miami Executive (KTMB) in IFR/VFR Charts databases. Refer to NOTAMs FDC 6/5251 and 6/5248 for the corrective action at [Federal Aviation Administration: NOTAM Search](#).

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

RESOLUTION

The updated charts will be included in cycle 2608 of the IFR/VFR Charts databases. Cycle 2608 IFR/VFR Charts databases are effective Aug 6, 2026 and will be available Aug 5, 2026.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING AN APPLICABLE IFR/VFR CHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."