

GARMIN®

Navigation Data Alert 26115

TO: Users of the Garmin Navigation Database
DATE: July 22, 2026
CYCLE: 2607
AIRPORT: TNCC - HATO CURACAO INTERNATIONAL
SUBJECT: Procedure Out of Date – Incorrect Fix Location

PRODUCT AFFECTED

Cycle 2607 of the Garmin Navigation Database (effective 09 JUL 2026 to 06 AUG 2026) is affected.



NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The following procedure and fix are incorrect.

Table 1.

Airport	Procedure	Fix	Error
TNCC	ABA1L Departure	ABA50	ABA50 fix in incorrect location and procedure out of date.

PILOT ACTION

Do not use the procedure or fix in any manner.

RESOLUTION

The procedure and fix will be corrected in the 2608 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://www.flygarmin.com) and select "Aviation Data Error Report."