

GARMIN®

SmartCharts Data Alert 26123

TO: Users of US and Worldwide Garmin Pilot™ App for iOS and Garmin Pilot Web

DATE: August 4, 2026

CYCLE: 2607 & 2608

SUBJECT: Missing & Incorrect Data Elements

PRODUCT AFFECTED

The Garmin SmartCharts procedures shown below in Garmin Pilot Mobile iOS and Garmin Pilot Web are affected:

- RNAV (GPS) Z RWY 22 at 3W7, Electric City, WA
- RNAV (RNP) Z RWY 08 at KABQ, Albuquerque, NM
- RNAV (GPS) RWY 21 at KBRG, Belen, NM
- RNAV (GPS) RWY 23 at KRAP, Rapid City, SD
- CHOTT 1 DEP (OBSTACLE) (RNAV) at O05, Chester, CA
- MOCAA 4 DEP (RNAV) at KTCM, Tacoma, WA

DESCRIPTION

- RNAV (GPS) Z RWY 22 at 3W7
 - The planview waypoint KLSEY is missing a speed restriction of AT/BEL 210K.
- RNAV (RNP) Z RWY 08 at KABQ
 - The published missed approach section in the details page is missing an additional note of 'Limit missed approach to 215K.'
- RNAV (GPS) RWY 21 at KBRG
 - When viewing the planview with the 'Vectors' or 'BUPNY' transition selected, a holding speed restriction of 210K is missing at the CESDA hold.
- RNAV (GPS) RWY 23 at KRAP
 - When viewing the planview with the 'Vectors' transition selected, a holding speed restriction of 175K is missing at the EWEBU hold.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://flygarmin.com) and select "Aviation Data Error Report."

GARMIN®

SmartCharts Data Alert 26123

- CHOTT 1 DEP (OBSTACLE) (RNAV) at O05
 - When viewing the planview with the 'All', 'RW16', or 'RW34' runway selected, multiple altitudes and speeds are missing.
 - The initial climb altitudes of AT/ABV 5040 are missing.
 - The DBOBO waypoint altitude and speed of AT/ABV 10000 and AT/BEL 250K are missing.
 - The CHOTT waypoint altitude of AT/ABV 10500 is missing.
- MOCAA 4 DEP (RNAV) at KTCM
 - When viewing the planview with the 'All' or 'IMB' transition selected, the altitude restriction at waypoint PAAGE is incorrect. The correct altitude restriction is AT/ABV 13100.

PILOT ACTION

Use these SmartCharts procedures with caution.

RESOLUTION

These SmartCharts procedures will be corrected in cycle 2609.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS USING GARMIN SMARTCARTS

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."