



JEPPesen®

NavData® Alert

!! URGENT !!

Date: 2 September 2026
Subject: Tirupati, India
Tirupati (VOTP)
Multiple procedures
Cycle 2609

Procedure information incorrect

Jeppesen NavData for cycle 2609, effective 3 September 2026, contains incorrect data for Tirupati, India (VOTP).

The following changes apply to the below listed procedures:

- **VOR Rwy 08:** stepdown fix **D7.2 TTP [72VOR]** with crossing altitude **at or above 1930'** should not be used.
- **VOR Rwy 26:** stepdown fix **D4.0 TTP [40VOR]** with crossing altitude **at or above 1780'** is missing from the database.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2610, effective 1 October 2026. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

VOTP_2609