



Navigation Data Alert 26159

TO: Users of the Garmin Navigation Database
DATE: September 28, 2026
CYCLE: 2609 & 2610
AIRPORT: KJYG
LOCATION: St. James, Minnesota
SUBJECT: Procedure with Incorrect Final Approach Fix Altitude

PRODUCTS AFFECTED

Cycle 2609 & 2610 of the Garmin Navigation Database (effective 03 SEP 2026 to 29 OCT 2026) are affected.



NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The following procedure has an incorrect altitude at the final approach fix.

Table 1.

Airport	Procedure	Correction
KJYG	RNAV (GPS) RWY 33	The correct procedural altitude at the final approach fix is at or above 2700 feet.

PILOT ACTION

Use the procedure with caution.

RESOLUTION

The procedure will be corrected in the 2611 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://www.flygarmin.com) and select "Aviation Data Error Report."