

GARMIN®

Navigation Data Alert 26156

TO: Users of the Garmin Navigation Database
DATE: September 21, 2026
CYCLE: 2609 & 2610
COUNTRY: Liberia
SUBJECT: Liberia AIRAC Supplement S02/20 was Received Late

PRODUCTS AFFECTED

Cycle 2609 & 2610 of the Garmin Navigation Database (effective 03 SEP 2026 to 29 OCT 2026) are affected.

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The following airway is out of date.

Airway	Correction
UY509	The following fixes are missing from airway UY509 between ROB VOR/DME and GATAX. The fixes are DIRDI, MOBMO, ONADA, INEGA, TERNA, and BOPRO. The course is unchanged.

PILOT ACTION

Use the airway with caution.

RESOLUTION

The airway will be corrected in the 2611 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground.
Go to [FlyGarmin.com](https://flygarmin.com) and select "[Aviation Data Error Report](#)."