

GARMIN®

Navigation Data Alert 26134

TO: Users of the Garmin Navigation Database
DATE: September 1, 2026
CYCLE: 2608 & 2609
AIRPORT: SAWB
LOCATION: Vicecomodoro Marambio - Antarctica
SUBJECT: Incorrect Fix Name

PRODUCT AFFECTED

Cycle 2608 and 2609 of the Garmin Navigation Database (effective 06 AUG 2026 to 01 OCT 2026) are affected.



NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The fix name listed below is incorrect.

Table 1.

Airport	Procedures	Correction
SAWB	RNP Z RWY 23 (LNAV)	The fix MINES has been replaced by the fix DAVID. The location of the fix DAVID is unchanged.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [FlyGarmin.com](https://flygarmin.com) and select "Aviation Data Error Report."

GARMIN®

Navigation Data Alert 26134

PILOT ACTION

Use the procedure with caution.

RESOLUTION

The procedure will be corrected in the 2610 cycle of the Garmin Navigation Database.

**THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS
UTILIZING THE GARMIN NAVIGATION DATABASE**

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."