

SafeTaxi Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot using the US, Americas, or Full Coverage SafeTaxi database
DATE: August 3, 2021
CYCLE: 21S4
SUBJECT: Corrected Airport Diagram for Republic, Farmingdale, NY (FRG)

DESCRIPTION

The FAA has advised Garmin that the digital-Terminal Procedures Publication, effective August 12, 2021, incorrectly depicted information on the AIRPORT DIAGRAM at Republic (KFRG), Farmingdale, NY. The airport diagram shows the incorrect depiction of runway 1-19 as it does not show the runway has moved north of its previous charted location.

The original safety alert can be seen at the following link:

https://www.faa.gov/air_traffic/flight_info/aeronav/safety_alerts/media/TERM_21-02_SA_FRG_AD.pdf

PILOT ACTION

Use extreme caution when referencing the airport layout at Republic (KFRG), Farmingdale, NY with cycle 21S4 US, Americas, or Full Coverage SafeTaxi.

RESOLUTION

The airport layout information will be corrected in the 21S5 cycle, effective October 7, 2021, of the US, Americas, and Full Coverage SafeTaxi databases for applicable Garmin aviation products and in Garmin Pilot.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE US, AMERICAS, OR FULL COVERAGE SAFETAXI DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."